

**MBW MOTORCYCLE PRODUCTS, INC.**

**IMPORTANT SAFETY NOTICE/RECALL**

**V1017: Vegas Rear License Plate Adapter**

**H1017: Hammer/Jackpot Rear License Plate Adapter**

**10/31/06** Effective immediately please be advised that MBW Motorcycle Products Inc., no longer authorizes the use, sale, or installation of our part numbers, V1017 (Vegas Rear License Plate Adapter) or H1017 (Hammer/Jackpot Rear License Plate Adapter) with our rear LED turn signal assemblies.

We were recently notified of breakage/failures of the mounting arms of an MBW rear LED turn signal assembly. This issue appears to be limited to the rear license plate adapters being used in conjunction with our newer style LED turn signals (starting in March 2006) which are one-piece injection molded plastic, as opposed to the previous version which used an aluminum mounting bracket. We caution **ALL** users of the rear license plate adapter to be advised of the potential problem. In addition, the use of any similar device, "home-made", etc., including dealer or other aftermarket company, is not authorized or appropriate for use with our rear LED turn signals. The rear LED turn signals are now designed, and should only be used, as a stand alone alternative to the stock rear turn signals, and nothing else.

We caution all owners/operators of motorcycles with our rear license plate adapter installed to remove them immediately and return them for a full purchase price refund or credit, not to exceed MSRP or inclusive of tax or other associated fees. No warranty or guarantee for the rear license plate adapter will be honored from this date forward, and owners/operators continuing to use them do so completely at their own risk. No additional costs associated with the removal/replacement of the rear license plate adapter, including but not limited to installation, labor, shipping, loss of use, or the purchase of additional products, etc. will be reimbursed. Reimbursement for the rear license plate adapter will only be issued or credited once it is received by MBW.

Authorized MBW dealers/distributors and/or any other persons or parties who have sold a rear license plate adapter, in whole or in part with any other products, are responsible for notifying any customers who would be affected by this recall.

Rear plate adapters should be returned directly to the vendor through which it was purchased for processing. Otherwise, users may ship the rear license plate adapter and proof of purchase to:

**MBW Motorcycle Products, Inc.**  
**ATTN: Warranty Service/Rear License Plate Adapter**  
**351 Liberty Lane, Unit 5-E**  
**West Kingston, RI 02892**

Please contact us @ [info@mbwmotorcycle.com](mailto:info@mbwmotorcycle.com) with any questions, thank you for your attention in this matter.